


Bulletin #2 - Engine noise found mostly in 2004 GM SUV's and Trucks using the OS-2BOSE.
Not a known issue in 2003 SUV's and Trucks.

Problem: A problem has arisen when installing the OS-2BOSE in 2004 SUV's and Trucks that engine noise is produced into the audio system. Currently, this is not a known problem in 2003 SUV's and Trucks. Please note that aftermarket flip out monitors may still require Bulletin #1 fix.

Solution: Use the supplied 1k ohm resistors and install them according to the diagram below.




6-21-04

Bulletin #2 - Engine noise found mostly in 2004 GM SUV's and Trucks using the OS-2BOSE.
Not a known issue in 2003 SUV's and Trucks.

Problem: A problem has arisen when installing the OS-2BOSE in 2004 SUV's and Trucks that engine noise is produced into the audio system. Currently, this is not a known problem in 2003 SUV's and Trucks. Please note that aftermarket flip out monitors may still require Bulletin #1 fix.

Solution: Use the supplied 1k ohm resistors and install them according to the diagram below.



6-21-04

