


Bulletin #1 - Engine whine using flip out video monitors from manufactures like Alpine, Kenwood, Pioneer, Clarion, etc.

Currently there is an issue using the OS-2BOSE with flip out monitors that uses a chassis that is mounted separately from the video monitor. Using the OS-2BOSE and flip out monitors usually results in engine whine. You can fix or reduce the engine whine by using a power noise filter like our CSS-12. Connect the noise filter as shown below.

Note:

1. If you are not experiencing any engine whine, you can disregard this bulletin.
2. As of now, there are currently no known issues with CD/MD/MP3 players built all in one chassis.




3-25-04

Bulletin #1 - Engine whine using flip out video monitors from manufactures like Alpine, Kenwood, Pioneer, Clarion, etc.

Currently there is an issue using the OS-2BOSE with flip out monitors that uses a chassis that is mounted separately from the video monitor. Using the OS-2BOSE and flip out monitors usually results in engine whine. You can fix or reduce the engine whine by using a power noise filter like our CSS-12. Connect the noise filter as shown below.

Note:

1. If you are not experiencing any engine whine, you can disregard this bulletin.
2. As of now, there are currently no known issues with CD/MD/MP3 players built all in one chassis.



3-25-04

